


凌科自动化
LATCOIS



■

i











DHCP **扫描** **下载** **监控** **参数** **描述文** **帮助**
服务 **模块** **参数** **件导入**

IP地址范围: 192 . 168 . 0 . 1 — 192 . 168 . 0 . 255

0%

开始 停止

LA_Config










简体中文

> LUC-CE(192.168.0.2)

0	1
LUC-CE	ES1160D



模块参数

模块类型: LUC-CE

物理地址: 7C-BA-CC-00-00-00

IP 地址: 192.168.0.2

子网掩码: 255.255.255.0

默认网关: 192.168.0.2

扩展数量: 1

固件版本: V1.01 Nov 18 2022 11:35:50

背板版本: NONE

I_SIZE(byte)	O_Size(byte)	C_Size(byte)
2	0	1

扩展模块信息

模块类型:

固件版本:

描述:

恢复参数默认值

IP地址分配方式 动态IP
 IP地址分配方式 静态IP
 安全模式 启用


<http://www.lancom.com>
Ver: 10.0 Build: com 2023.03.01 14:53:07

DHCP

	MAC	IP	状态
1	7C : BA : CC : 15 : 82 : 3E	192 . 168 . 0 . 1	未分配

添加MAC
删除MAC

启动服务
关闭服务

加载配置
保存配置

DHCP 启动时, 启模块中, 源被分配新的IP地址

信息栏



DHCP

	MAC	IP	状态
1	7C : BA : CC : 15 : 82 : 3E	192 . 168 . 0 . 3	分配成功

添加MAC
删除MAC

启动服务
关闭服务

加载配置
保存配置

DHCP 启动时, 启模块中, 源被分配新的IP地址

信息栏

```

[23-Mar-23 10:50:19] Warning: Interface 192.168.10.19 is not Static, ignored
[23-Mar-23 10:50:19] Lease URL: http://127.0.0.1:6789
[23-Mar-23 10:50:19] Listening On: 192.168.0.211
[23-Mar-23 10:50:20] DHCPREQUEST for 7c:ba:cc:15:82:3e () from interface 192.168.0.211 received
[23-Mar-23 10:50:20] Host 7c:ba:cc:15:82:3e (Host7cbacc15823e) allotted 192.168.0.3 for 3600
seconds
[23-Mar-23 10:50:20] Network ok, ready to start testing.
  
```



mac	IP地址	子网掩码	默认网关	模块名称	状态
-----	------	------	------	------	----

扫描时间 5 :S

全局扫描 修改IP 恢复出厂设置 重启模块

mac	IP地址	子网掩码	默认网关	模块名称	状态
1 7C-BA-CC-00-00-00	192 . 168 . 0 . 2	255 . 255 . 0 . 0	192 . 168 . 0 . 2	LINKSYS WRT54GL	未操作

扫描时间 5 :S

扫描进行中:

全局扫描 修改IP 恢复出厂设置 重启模块



